Subject photos



Aerial view of the subject property, which is outlined in red.



The subject property. Photo taken from S. Railroad Street.

Taken by: JWT




Subject Photo # 3

Photo of the rear side of building. Photo taken from the middle of the subject parcel looking easterly.



Street scene.
Photo looking south along S.
Railroad Street (US 28). Subject property can be seen on right side of photo.

Taken by: JWT



Subject Photo # 5


Looking north along the subject's frontage along S. Railroad Street (Highway 28).

Photo taken from near the northeastern most corner of the subject site.



Photo of the office area of the improvement. Recessed area at back leads to restroom.

Taken by: JWT



Subject Photo # 7

Wood panel interior finish found in office area. Wall mount heater can be seen in center of photo.



Photo of restroom located adjacent to office area.

Taken by: JWT




Subject Photo #9

Photo of the interior of the warehouse area. Pendant heaters can be seen at top right of photo.



Photo of the interior of the warehouse area.

Taken by: JWT



Subject Photo # 11

Photo of the storage area adjacent the office area.



Site photo.
Looking east along the southern boundary of the subject site.
Exterior fencing can be seen at right side of photo.
Built up area in center of photo serves as a quasiloading ramp.

Taken by: JWT



Subject Photo # 13

Photo of western most boundary of the site looking north. Exterior perimeter fencing can be seen at left side of photo.




Photo of the above ground fuel pump situated right above the underground fuel storage tank. Some discoloration can be seen at bottom of the fuel pump.

Taken by: JWT



Subject Photo # 15

Electrical system and emergency shut off valve for fuel pump.